

Review these instructions to see how easy it is to care for a Transolid® Solid Surface product.

### Everyday Cleaning

- Wipe the surface with a damp cloth or sponge.
- For basic stains, clean with mild detergent or general purpose cleaner.
- For cleaning corners and seams, spray with mildew cleaner.  
*With regular maintenance spraying, there should be no need to scrub any silicone caulk joints.*

### Removing Persistent Stains, Burns or Light Scratches

- Scrub surface in a circular motion with an abrasive cleaner and a wet, green Scotch-Brite® pad.  
(See Note below)
- For best results, repeat the above step with a wet, gray Scotch-Brite® pad.
- On darker\* colored products, repeat with a wet, white Scotch-Brite® pad.

### Scratches in the Surface

- Lightly sand the surface in a circular motion with 120-grit sandpaper.
- Repeat this step, using 220-grit sandpaper and then 320-grit sandpaper.
- Complete the process by scrubbing the surface in a circular motion with a wet, green Scotch-Brite® pad and then with a wet, gray Scotch-Brite® pad. On darker colored products, repeat with a wet, white Scotch-Brite® pad.

### Tips to Avoid Damage

- Avoid cutting directly on the surface of the Transolid product.
- Wipe away strong acids, such as those found in drain cleaners. Some of these acids, when left on the surface, may cause whitening which can be difficult to remove.

Note: Scotch-Brite® is a registered trademark of 3M and the green, gray, and white pads may be purchased at most specialty hardware or building supply stores. Start with the more coarse pad (green) and work down to the finer grit pads (gray and then white).

\*Darker colored Transolid products include the following: Matrix Pink, Matrix Jade, Matrix Light Gray, Matrix Dark Gray, Matrix Green, Matrix Light Blue, Matrix Dark Blue, Deep Sea, Spruce, Graphite, Midnight, Venetian, Aztec, Sage, Harbor Gray, Shore Road, Silt Stone, Ocean Pines, and all of the Natural Selections colors.